

# BIO-DEX



## Aquadex 50 STAIN OFF

- 1 qt. treats 10,000 gallons. Maintenance dose: 4 oz. per 10,000 gallons weekly.
- An excellent product for removal of metallic stains from spas & pools.
- Stable at high temperatures and is unaffected by chlorine, acid or other sanitizing chemicals.
- Mixes very rapidly with pool water. Swimming may begin or continue 30 minutes after treatment.
- Add to Bio-Dex Plaster White 'n Brite Acid Wash for EXTREME Clean!

Removes Black Cobalt Stains from Fiberglass  
Spas and Swimming Pools  
Removes Copper and Iron Stains from  
Swimming Pool Plaster

## AQUADEX 50 STAIN OFF

*Aquadex 50* is an excellent aid for removal of metallic stains from spas and swimming pools and can be added to Plaster White 'n Brite for EXTREME clean.

*Aquadex 50* is stable at high temperatures and is unaffected by Chlorine, Acid or other sanitizing chemicals.

*Aquadex 50* goes into solution with pool water rapidly and swimming may continue 30 minutes after treatment.

### Directions

To treat black cobalt stains in fiberglass spas and swimming pools, and to remove copper and iron stains from plastered swimming pools and spas, do as follows:

### Fiberglass Spas Initial Dose:

Add 8 oz. per 500 gallons of spa water. Circulate the spa water for 5 minutes. If stain persists after 48 hours, repeat treatment.

### Maintenance Dose:

Spas - Add 2 oz. weekly per 500 gallons of spa water. Maintain pH level between 7.2 and 7.6.

### Fiberglass and Plastered Swimming Pools Initial Dose:

Add 1 quart (32 fl. oz.) per 10,000 gallons pool water. Allow filter system to operate 8 hours after treatment. Pour Aquadex 50 Stain-Off into water area where staining is most severe. If stains persist, repeat dosage after 48 hours. Maintain a pH level of between 7.2 and 7.6.

### Maintenance Dose:

Pools - Add 4 oz. weekly per 10,000 gallons of water.

*Do not mix or premix Aquadex 50 Stain-Off with other water treatment chemicals. Aquadex 50 Stain-Off may be added to Bio-Dex Plaster White 'n Brite working as a booster to remove difficult copper and iron stains completely during an acid wash. Always use protective eye goggles and rubber gloves when using Aquadex 50 Stain-Off.*

### Ordering Information:

(623) 582-2400 • (800) 617-3477

E-mail: [bio-dex@bio-dex.com](mailto:bio-dex@bio-dex.com) • Website: [www.bio-dex.com](http://www.bio-dex.com)

THANK YOU FOR CHOOSING BIO-DEX!